



## Disposição



DISPOSIÇÃO ALTERNADA - SEXTAVADA

Furos em ângulo de 60° equidistantes entre si.



DISPOSIÇÃO RETA OU QUADRADA

## Tabela

Diâmetros		Centros mm	Área aberta %
mm	Polegadas		
0,5	.020	1,0	20
0,5	.020	1,25	14
0,6	.023	1,2	23
0,6	.023	1,35	17
0,7	.028	1,6	17
0,8	1/32	1,6	23
0,9	.035	1,8	23
*1,0	.040	1,6	35
1,0	.040	1,77	28
1,0	.040	1,9	25
1,1	.043	2,0	27
1,2	.3/64	2,2	27
1,3	.051	2,4	26
1,4	.055	2,4	31
1,5	.059	3,0	23
1,5	.059	3,18	20
1,6	1/16	3,0	26
1,8	.071	2,55	45
1,8	.071	3,0	32
2,0	5/64	3,0	40
2,0	5/64	3,5	29
2,0	5/64	4,0	23
2,4	3/32	4,0	32
2,4	3/32	5,0	21
2,8	7/64	4,0	44
3,2	1/8	5,0	36
3,2	1/8	6,0	25
3,6	9/64	5,0	47
4,0	5/32	6,0	40
4,0	5/32	7,0	29
4,8	3/16	7,0	42
4,8	3/16	8,0	32
4,8	3/16	10,0	21

Diâmetros		Centros mm	Área aberta %
mm	Polegadas		
8,0	5/16	14,0	29
9,5	3/8	13,0	48
9,5	3/8	14,0	41
9,5	3/8	16,0	32
11,1	7/16	16,0	43
12,7	1/2	18,0	45
12,7	1/2	20,0	36
12,7	1/2	24,0	25
14,3	9/16	20,0	46
14,3	9/16	22,0	38
16,0	5/8	20,0	57
16,0	5/8	24,0	40
17,5	11/16	28,0	35
19,0	3/4	26,0	48
19,0	3/4	32,0	32
19,0	3/4	34,0	28
22,2	7/8	28,0	57
22,2	7/8	32,0	43
25,4	1	32,0	57
25,4	1	38,0	40
28,6	1.1/8	40	46
30,2	1.3/16	42	46
31,8	1.1/4	48	40
35	1.3/8	52	41
38,1	1.1/2	56	42
41,3	1.5/8	58	46
44,4	1.3/4	62	46
47,6	1.7/8	66	47
50,8	2	72	45
57	2.1/4	76	51
63,5	2.1/2	84	51
66,7	2.5/8	88	52
69,8	2.3/4	92	52

Diâmetros		Centros mm	Área aberta %
mm	Polegadas		
5,55	7/32	8,0	43
5,55	7/32	10,0	28
6,35	1/4	9,0	45
6,35	1/4	10,0	36
6,35	1/4	11,0	30
8,0	5/16	11,0	48
8,0	5/16	12,0	40

Diâmetros		Centros mm	Área aberta %
mm	Polegadas		
76,2	3	96	54
82,6	3.1/4	104	57
88,9	3.1/2	110	59
95,2	3.3/4	120	57
101,6	4	124	74
108,0	4.1/4	130	62